

891805-A0 Electronic Unit Injector Repair Kits A0 Series

Technical File

SKU: G1Y300891805A0



891805-A0 Electronic Unit Injector Repair Kits A0 Series

Technical File

Content

1. 891805-A0 Electronic Unit Injector Repair Kits Introduction	1
1.1. 891805-A0 Electronic Unit Injector Repair Kits Basic Information	1
1.2. 891805-A0 Electronic Unit Injector Repair Kits Common Part Number	1
1.3. 891805-A0 Electronic Unit Injector Repair Kits Parameter	1
1.4. 891805-A0 Electronic Unit Injector Repair Kits Specifications and Dimensions	1
1.5. 891805-A0 Electronic Unit Injector Repair Kits Quality Control	1
1.6. 891805-A0 Electronic Unit Injector Repair Kits Customized Service	2
1.7. 891805-A0 Electronic Unit Injector Repair Kits Packing List and Package Size	2
1.8. 891805-A0 Electronic Unit Injector Repair Kits Packing Testing Standard and Certificate	4
1.9. 891805-A0 Electronic Unit Injector Repair Kits Warranty Instructions	4
1.10. 891805-A0 Electronic Unit Injector Repair Kits Manufacturer	5
2. 891805-A0 Electronic Unit Injector Repair Kits Technical Support	5
2.2. 891805-A0 Electronic Unit Injector Repair Kits Not Working Normally	6
2.3. 891805-A0 Electronic Unit Injector Repair Kits Causes of Being Damaged	6
2.4. 891805-A0 Electronic Unit Injector Repair Kits Technical Support Obtaining Methods	7
3. 891805-A0 Electronic Unit Injector Repair Kits Purchase and Delivery	7
3.1. 891805-A0 Electronic Unit Injector Repair Kits Purchase Payment Term	7
3.2. 891805-A0 Electronic Unit Injector Repair Kits Main Sales Markets	7
3.3. 891805-A0 Electronic Unit Injector Repair Kits Declaration Requirements	7
3.4. 891805-A0 Electronic Unit Injector Repair Kits Shipping Ways	8
3.5. 891805-A0 Electronic Unit Injector Repair Kits Lead time	8
3.6. 891805-A0 Electronic Unit Injector Repair Kits Logistics Time for Destination Out of China's Areas	8
3.7. 891805-A0 Electronic Unit Injector Repair Kits Packing	9
4. 891805-A0 Electronic Unit Injector Repair Kits Storage Standard	9
5. Company Information	10
5.1. Company Introduction	10
5.2. Salesmen's Contact Information	11
6. Copyright Statement	11

891805-A0 Electronic Unit Injector Repair Kits A0 Series Technical File

1. 891805-A0 Electronic Unit Injector Repair Kits Introduction

1.1. 891805-A0 Electronic Unit Injector Repair Kits Basic Information

Title	891805-A0 Electronic Unit Injector Repair Kits A0 Series	Quality
SKU	G1Y300891805A0	China Made New

1.2. 891805-A0 Electronic Unit Injector Repair Kits Common Part Number

(1) Electronic Unit Injector Repair Kits Exchange Information

Electronic Unit Injector Repair Kits Part Number	Compatible Part Number
891805-A0	/

(2) Electronic Unit Injector Repair Kits Application Information

Electronic Unit Injector Part Number	OE Number	Engine Model
/	/	/

(3) Electronic Unit Injector Repair Kits Part Number Common Writing

891805-A0

1.3. 891805-A0 Electronic Unit Injector Repair Kits Parameter

Adaptation System: Common Rail System

Electronic Unit Injector Repair Kits Series: A0 Series

Electronic Unit Injector Repair Kits Type: High Pressure Common Rail Electronic Unit Injector Repair Kits

1.4. 891805-A0 Electronic Unit Injector Repair Kits Specifications and Dimensions

Electronic Unit Injector Repair Kits Size: 7cm*6 cm *1 cm

Electronic Unit Injector Repair Kits Net Weight: 20g

Electronic Unit Injector Repair Kits Gross Weight: 50g

Electronic Unit Injector Repair Kits Quality: China Made New

Electronic Unit Injector Repair Kits Box Size: 10cm* 9cm *1cm

Electronic Unit Injector Repair Kits MOQ: 10 Pieces

1.5. 891805-A0 Electronic Unit Injector Repair Kits Quality Control

(1) Electronic Unit Injector Repair Kits Testing

All electronic unit injector repair kits spare parts are tested for electrical characteristics, accuracy, high temperature, low temperature, withstand voltage, leakage, durability, and various working conditions.

(2) Electronic Unit Injector Repair Kits Assembling

For the quality control of electronic unit injector repair kits production and installation, our company strictly conducts installation per the standard installation parameters and procedures, covering the stroke


test and fatigue spring test of the electronic unit injector repair kits.

(3) Electronic Unit Injector Repair Kits Inspection

The factory inspection of the electronic unit injector repair kits is undergone full inspection, random inspection, and batch inspection three inspections. Different brands of test benches are used to test the same electronic unit injector repair kits for more than three times for factory inspection, and the electronic unit injector repair kits installation testing environment are progressed in dust-free workshop.

1.6. 891805-A0 Electronic Unit Injector Repair Kits Customized Service

(1) Electronic Unit Injector Repair Kits Customized Service: Meet the customized needs of OEM manufacturers for shell lettering, logo engraving, electronic unit injector repair kits internal packaging, electronic unit injector repair kits external packaging and labels customized, etc.



(2) Electronic Unit Injector Repair Kits Customized Service Requirements:

The purchased of customized electronic unit injector repair kits are not less than **10 pieces**.

Customized electronic unit injector repair kits packages no less than **1000 pieces**.

When the customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

⚠ Once the customized electronic unit injector repair kits is sold, it cannot be returned or exchanged if there is no quality problems.

1.7.891805-A0 Electronic Unit Injector Repair Kits Packing List and Package Size

(1) Electronic Unit Injector Repair Kits Spare Parts List

No.	1	2	3
Image			
Name	Electronic Unit Injector Repair Kits Assembly	Desiccant	White Rust-proof Bag
Description	Electronic unit injector repair kits part number: 891805-A0	Prevents rust, absorbs moisture	Electronic unit injector repair kits from rusting

No.	4	5	6
Image			/
Name	Electronic Unit Injector Repair Kits Packaging	Electronic Unit Injector Repair Kits	/
Description	Placement electronic unit injector repair kits	Complete accessories 21pcs	/

⚠ Minors are prohibited from using electronic unit injector repair kits assemblies, desiccant and VCI rust-proof bags to prevent personal injury.

⚠ O-rings, desiccants, and VCI rust-proof bags are disposable installation accessories and need to be replaced upon reinstallation.

⚠ VCI rust-proof bags and desiccant are made of non-degradable materials and should be disposed of properly after use.

⚠ When installing the electronic unit injector repair kits and the connecting pipes, apply an appropriate amount of sealing oil.

(2) Electronic Unit Injector Repair Kits Packing Box Size



Name	Electronic Unit Injector Repair Kits Packing Box Size (cm)
Electronic Unit Injector Repair Kits Packing Box	10*9*1

1.8.891805-A0 Electronic Unit Injector Repair Kits Packing Testing Standard and Certificate

Shumatt can provide the factory quality inspection test report of each electronic unit injector repair kits to ensure that each electronic unit injector repair kits delivered meets the engine performance indicators.

BOTEN		测试报告		4.05.2019 10:42:09	
承修企业: _____					
电话: _____		地址: _____			
传真: _____		检测人: _____			
客户地址: _____		检测单位: _____			
电话: _____		客户姓名: _____			
传真: _____		检测日期: _____			
检测项目: _____					
检测名称: _____					
型号-零件号: _____					
检测地点: _____					
检测结果					
检测标准: C95002-6511					
	检测项目	检测结果	标准值	判定	
ICAR TEST:	38	4	4.5	合格	✓
Back:	38	4	4.5	合格	✓
WARM:	38	4.5±0.5	4.5	合格	✓
Max:	211.5	211.5±14.4	211.5	合格	✓
TL:	28.4	28.4±0.5	28.4	合格	✓
UL:	14.1	14.1±0.5	14.1	合格	✓
VE:	4.7	4.7±0.5	4.7	合格	✓
检测人: _____ 检测日期: _____					

1.9.891805-A0 Electronic Unit Injector Repair Kits Warranty Instructions

(1) Product Warranty Conditions and Instructions

It is necessary to provide pictures, videos, or test reports detected by the electronic unit injector repair kits inspection equipment when the electronic unit injector repair kits is abnormal during use as evidence to feed back to the salesman.

Abnormal conditions are properly explained such as: 1.Smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. oil leakage etc.

(2) Electronic Unit Injector Repair Kits Warranty Coverage

Within 15 days after customer receives the 891805-A0 injector, if there is a performance failure and the product has no appearance damage, customer can choose to replace it or repair it;

If the 891805-A0 electronic unit injector repair kits has performance problems during the warranty period (6-12 months), and it is confirmed that it is product's problems after testing, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;

If the electronic unit injector repair kits house has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

▲ Tips: For products not covered by warranty, our company can provide paid maintenance services. For products after paid repaired, the same performance problem will have a free warranty period within 3 months from the date of repairing.

(3) Electronic Unit Injector Repair Kits Out of Warranty Coverage

- ① The warranty period has expired and is not covered.
- ② Electronic unit injector repair kits failure caused by high temperature, high pressure, humidity, rain, snow, saline-alkali soil, earthquakes, or abnormal environments.
- ③ Electronic unit injector repair kits damage caused by unauthorized disassembly or repair by the customer.
- ④ Electronic unit injector repair kits damage caused by human error (dropping, magnetization by a strong magnetic field, arson).
- ⑤ Electronic unit injector repair kits failure or damage caused by issues other than the injector electronic unit injector repair kits's design, technology, manufacturing, or quality.
- ⑥ Electronic unit injector repair kits failure caused by system pressure exceeding the approved system pressure.
- ⑦ Electronic unit injector repair kits failure caused by system voltage exceeding the approved voltage.
- ⑧ Electronic unit injector repair kits failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.
- ⑨ Electronic unit injector repair kits failure caused by installation not following the tightening torque specified in the vehicle's engine maintenance manual (excessive or insufficient tightening torque).
- ⑩ Electronic unit injector repair kits failure due to failure to adhere to the installation angle specified in the vehicle engine maintenance manual.
- ⑪ Failure to adhere to the cleaning requirements specified in the vehicle engine maintenance manual.
- ⑫ Failure to follow the replacement requirements for wearing parts specified in the vehicle engine maintenance manual.
- ⑬ Failure to adhere to the intake and exhaust system clearance requirements specified in the vehicle engine maintenance manual.
- ⑭ Failure to follow the replacement requirements for wearing parts in the oil system and the clearances between the oil intake system piping and the electronic unit injector repair kits.

1.10. 891805-A0 Electronic Unit Injector Repair Kits Manufacturer

Electronic Unit Injector Repair Kits Manufacturer: Shenzhen Shumatt Technology Co., Ltd

2. 891805-A0 Electronic Unit Injector Repair Kits Technical Support

2.1. 891805-A0 Electronic Unit Injector Repair Kits Installation

(1) 891805-A0 Electronic Unit Injector Repair Kits Installation Precautions:

- ① The replacement of the electronic unit injector repair kits must strictly follow the electrical system, the approved pressure of the low-pressure fuel intake system, the approved pressure of the high-pressure fuel circuit system, and fuel system replacement consumables requirements (including the low-pressure fuel circuit system filter and the high-pressure fuel circuit) specified in the vehicle engine maintenance

manual.

② Replacement of wearing parts of the fuel system, cleaning requirements for the connection between the fuel system and the electronic unit injector repair kits, the fitting clearance of the electronic unit injector repair kits connection, the installation angle and tightening torque of the electronic unit injector repair kits, the fitting clearance of the intake system, and the fitting clearance of the exhaust system to ensure the service life of the engine and the normal operation of the electronic unit injector repair kits.

③ When installing the electronic unit injector repair kits on the engine, it is necessary to clean the engine block, cylinder head and other parts connected to the electronic unit injector repair kits, and ensure that there is no dust, carbon deposits, water, rust spots, etc.

④ When installing the electronic unit injector repair kits on the engine, please carefully check the components related to the installation of the electronic unit injector repair kits, such as the electronic unit injector repair kits pressure plate, screw, electronic unit injector repair kits rod and other accessories are not deformed, and install it in strict accordance with the operation steps of the engine maintenance manual.

⑤ It is forbidden to operate the bare electronic unit injector repair kits for a long time in an environment with serious dust pollution and corrosion to iron products.

⑥ It is forbidden to operate the bare electronic unit injector repair kits for a long time in a strong magnetic field environment.

2.2. 891805-A0 Electronic Unit Injector Repair Kits Not Working Normally

- (1) There is air in the oil circuit of the engine fuel system.
- (2) Vehicle electronic unit injector repair kits's oil supply system is not normal.
- (3) Engine common rail system oil leakage or pressure limiting valve damage.
- (4) There is a short circuit, cutting out and poor contact in the wiring harness connected to the electronic unit injector repair kits of the vehicle.
- (5) The long-term placement of the electronic unit injector repair kits causes the anti-rust oil to solidify, and the internal components are stuck or the oil holes are blocked.

▲ Before installing, carefully check whether other components in the common rail system except the electronic unit injector repair kits are damaged to prevent the electronic unit injector repair kits from not working properly after being replaced.

2.3. 891805-A0 Electronic Unit Injector Repair Kits Causes of Being Damaged

- (1) Didn't operate properly according to engine maintenance manual during disassembly or installation, resulting in damage to the electronic unit injector repair kits.
- (2) The fuel oil used for the vehicle does not meet the standard cause damage to the electronic unit injector repair kits, such as: the water content in the fuel oil exceeds the standard, iron powder, aluminum powder, sulfide impurities exceed the standard, etc.
- (3) The engine is not regularly maintained according to the engine maintenance manual (please refer to the vehicle maintenance manual for the maintenance mileage). For example, failure to replace the lubricating oil of the engine system for a long time will cause abnormal wear of the engine, excessive exhaust gas volume or a large amount of carbon deposits inside the engine. The filter is not replaced during maintenance or the replaced filter cannot reach the original filter standard. all above reasons can cause damage to the electronic unit injector repair kits.
- (4) The abrasion of the electronic unit injector repair kits produces iron powder and aluminum powder enter the electronic unit injector repair kits and cause damage to the electronic unit injector repair kits.

- (5) The deformation and abrasion of fuel tank result in iron powder or aluminum powder entering the electronic unit injector repair kits and causing damage to the electronic unit injector repair kits.
- (6) The electronic unit injector repair kits is damaged due to replacement or adjustment of the relevant parts of the electronic unit injector repair kits. For example, the valve clearance does not meet the standard after the engine is repaired, the replacement or modification of the wiring harness connected to the electronic unit injector repair kits fails to meet the original standard.
- (7) The engine is overheated and overloaded for a long-time working result in damage to the electronic unit injector repair kits.
- (8) The electronic unit injector repair kits will be damaged naturally at the end of its working life.
- (9) The electronic unit injector repair kits is magnetized (electronic unit injector repair kits parts' magnetic exceeded) causing the electronic unit injector repair kits to not work properly.

▲ Before replacing the electronic unit injector repair kits, please check the engine parts carefully according to the engine maintenance manual to avoid the electronic unit injector repair kits being damaged again after replacement.

2.4. 891805-A0 Electronic Unit Injector Repair Kits Technical Support Obtaining Methods

- (1) Electronic Unit Injector Repair Kits Technical File , visit <http://shumatt.com> to get the technical file.
- (2) Electronic Unit Injector Repair Kits Technical Videos

Facebook: Visit <https://www.facebook.com/hison.li> to get the technical videos, constantly follow can get more information.

YouTube: https://www.youtube.com/channel/UCByvYBx7VjV_mAfxh_Hu-aw to get the technical videos, constantly follow can get more information.

Shumatt: Visit <http://shumatt.com> to get the technical videos.

- (3) Electronic Unit Injector Repair Kits Information Query Software
TruckBook Parts EPC APP, Android/Apple App Store download and install, visit <http://shumatt.com> to get the download and installation tutorial
- (4) Search The Electronic Unit Injector Repair Kits Test Data Through TruckBook Parts EPC APP.

3.891805-A0 Electronic Unit Injector Repair Kits Purchase and Delivery

3.1.891805-A0 Electronic Unit Injector Repair Kits Purchase Payment Term

Payment Terms: T/T, PayPal, Alipay, WeChat

▲ Please contact our salesmen for specific payment information.

3.2.891805-A0 Electronic Unit Injector Repair Kits Main Sales Markets

Electronic unit injector repair kits main sales markets: Asia, Europe, North America, South America, Africa etc.

3.3.891805-A0 Electronic Unit Injector Repair Kits Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4. 891805-A0 Electronic Unit Injector Repair Kits Shipping Ways

Destination in China areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

Destinations out of China's areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

3.5. 891805-A0 Electronic Unit Injector Repair Kits Lead time

Lead time: Send out within 3 – 7 working days after receiving payment (Except for special products and special cases) .

3.6. 891805-A0 Electronic Unit Injector Repair Kits Logistics Time for Destination Out of China's Areas

DHL Logistics Time :

Country or Region of Departure	Hong Kong, China	Other Countries or Regions of Asia	Australia and New Zealand	Europe	America	Other Countries
China's Mainland	7 Days	7 Days	8 Days	8 Days	8-12 Days	7-10 Days

UPS Logistics Time: Country or Region of Departure: China's Mainland

Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time
Japan	3 Days	UK	5-7Days	Egypt	5-7 Days
Turkey	5-7 Days	Singapore	3 Days	Switzerland	5-7 Days
Bahrain	5-7 Days	Latvia	7-10 Days	New Zealand	7-10 Days
Sri Lanka	5-7 Days	Thailand	3 Days	Austria	5-7 Days
Romania	5-7 Days	Vietnam	3-5 Days	Estonia	5-7 Days
Malaysia	3-5 Days	Israel	5-7 Days	Mexico	7-10 Days
France	5-7 Days	America	5-7 Days	United Arab Emirates	5-7 Days
Italy	5-7 Days	Netherlands	5-7 Days	Bengal	7-10 Days
Lebanon	5-7 Days	Philippine	3-5 Days	Greece	7-10 Days
South Korea	3 Days	Spain	5-7 Days	Myanmar	5-7 Days
Canada	5-7 Days	Germany	5-7 Days	Saudi Arabia	7-10 Days
Portugal	5-7 Days	Australia	5-7 Days	South Africa	7-10 Days
Denmark	5-7 Days	Belgium	5-7 Days	Ukraine	7-10 Days
India	7-10 Days	Qatar	7-10 Days	Poland	5-7 Days
Indonesia	3-5 Days	Morocco	7-10 Days	Pakistan	7-10 Days
Kuwait	7-10 Days	/	/	/	/

⚠ The logistics time is for reference only , subjects are according to the actual arrival.

3.7. 891805-A0 Electronic Unit Injector Repair Kits Packing

Domestic express packaging: Usually wrapped in waterproof scotch tape, such as picture No.1.

International express packaging: Wrapped with waterproof yellow tape After wrapping the black protective film, such as picture No. 2.

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 3, also, the products can be packaged according to customers' requirements.

⚠ The packing tray is made of plastic and can be recycled.

⚠ Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non-degradable materials, please dispose of them properly.

⚠ Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.

No.	1	2	3
Image			
Name	Domestic Express Packaging	International Express Packaging	Pallet Shipping
Description	Wrapped by transparent tape	Wrapped with yellow tape after wrapping black protective film	Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties

4.891805-A0 Electronic Unit Injector Repair Kits Storage Standard

(1) Choose a suitable storage place

The warehouse and cargo yard where the electronic unit injector repair kits is stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acids, alkalis, salts and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

(2) Strict requirements of warehousing

Strict inspections should be carried out when the electronic unit injector repair kits are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. Packaged injectors must be protected from damage.

(3) Keep the warehouse dry and preventing moisture

The relative humidity is usually below 70% for the electronic unit injector repair kits placed in the room,

and the corrosion of the electronic unit injector repair kits are significantly reduced.

Electronic unit injector repair kits must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content.

(4) Stack Properly

After the electronic unit injector repair kits is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the electronic unit injector repair kits from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse.

If the electronic unit injector repair kits package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

- ⚠ It is forbidden to leave the electronic unit injector repair kits exposed in the air for a long time.
- ⚠ It is forbidden to store acid, alkali, salt and other substances together with the electronic unit injector repair kits.
- ⚠ The unpacked electronic unit injector repair kits must be rust-proof during secondary storage.

5. Company Information



5.1. Company Introduction

Chinese Name: 深圳市舒马特科技有限公司

English Name: Shenzhen Shumatt Technology Co., Ltd

📞 **Mob Phone/WeChat:** +86-13410541523

📞 **HK Telephone:** +852-67653519

☎ **Telephone:** +86-755-23215133

Mob/WhatsApp: +86 13410541523

Email : ruby@shumatt.com

© 2026 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

Website : www.shumatt.com

 **Email:** ruby@shumatt.com

 **Website:** www.shumatt.com

 **Shenzhen Office:** 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station, Bao'an District, Shenzhen, China's Mainland

 **Shenzhen Office:** Exit C, Qiao Touxu Metro Station, NO. 66 Chongqing Road, Fuhai Avenue, Bao'an District, Shenzhen, China Mainland

 **Hong Kong Office:** Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

 **After-sales Service Address:** Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: [1.9. 891805-A0 Electronic Unit Injector Repair Kits Warranty Instructions](#))

5.2. Salesmen's Contact Information

No.	Name	WeChat/WhatsApp	Email
1	Ruby	+86-13410541523	ruby@shumatt.com
2	Ivy	+86-18025299821	sales@shumatt.com
3	Rebecca	+86-18025349821	sales01@shumatt.com
4	Janny	+86-18028749821	sales02@shumatt.com
5	Sam	+86-13316859821	Sales8@shumatt.com
6	Natalie	+86- 18938945856	sales15@shumatt.com
7	Ada	+86-1342286353	sales5@shumatt.com
8	Hison Li	+86-18318811871	web@shumatt.com
9	Mecca	+86-18938948618	sales11@shumatt.com
10	Eric	+86 18319033618	sales3@shumatt.com
11	Wayne (Joaquín en español)	+86-13316959821	wayne@shumatt.com
12	Sylvia	+86 18312499884	sales6@shumatt.com
Visit http://shumatt.com to obtain the latest information of salesmen			
PS: Shumatt's salesmen's emails are all end with @shumatt.com			

6. Copyright Statement

The copyright of any contents (including but not limited to parameters, data, text, charts, images, sounds or videos, etc.) provided in “**891805-A0 Electronic Unit Injector Repair Kits A0 Series Technical File**” belong to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify any contents in “**891805-A0 Electronic Unit Injector Repair Kits A0 Series Technical File**” in any way. At the same time, any conditions to spread, repost, display the contents of “**891805-A0 Electronic Unit Injector Repair Kits A0 Series Technical File**” should

indicate that the cited article is from Shenzhen Shumatt Technology Co., Ltd., Any actions failure to follow above conditions to use “891805-A0 Electronic Unit Injector Repair Kits A0 Series Technical File” will violate the “Copyright Law of the People's Republic of China” and other laws and regulations and the provisions of relevant international conventions.